

Southern California Edison Company

P. O. BOX 800

2244 WALNUT GROVE AVENUE ROSEMEAD, CALIFORNIA 91770

March 14, 1995

Mr. Emmanuel Mensah
Waste Management Engineer
California Environmental
Protection Agency
Department of Toxic Substances Control
10151 Croydon Way, Suite 3
Sacramento, Ca 95827

Subject:

VISALIA POLE YARD

REPORT OF REMOVAL ACTION

Dear Mr. Mensah:

Enclosed for your approval are two copies of the report that details the remedial actions taken for the hydrocarbon contamination at the Visalia Service Center (VSC) garage and the former pole yard office. The completed work described in this report was outlined in the Work Plan submitted to you in November, 1994.

As indicated by the data in the attached report, hydrocarbon contamination in the two subject areas has been removed and the areas should be released from regulatory concern. Contaminated soil from the described removal actions has been deposited in the existing on-site landfarm treatment area for bioremediation.

Southern California Edison is requesting the Department's timely concurrence that the subject areas at the Visalia Pole Yard are no longer of regulatory concern.

If you have any questions, I can be reached at (818) 302-2216.

Sincerely,

George M. Becker Senior Environmental Specialist

· cc:

Mr. Dick Procunier, USEPA, Region IX

Mr. Eric Becker, Central Valley RWQCB

Mr. R.S. Weidner (for file)



Southern California Edison Company

P. O. BOX 800

2244 WALNUT GROVE AVENUE ROSEMEAD, CALIFORNIA 91770

REPORT OF REMOVAL ACTION AND INITIATION OF REMEDIATION SOILS CONTAINING PETROLEUM HYDROCARBONS FORMER GARAGE AND POLE YARD OFFICE SOUTHERN CALIFORNIA EDISON VISALIA POLE YARD

432 North Ben Maddox Way Visalia, California

Submitted To:

California EPA
Department of Toxic Substances Control
Site Mitigation Unit
10151 Croydon Way
Sacramento, CA 95827

Prepared By:

SCE Environmental Engineering 2244 Walnut Grove Avenue, Room 405 Rosemead, California 91770

March 13, 1995

REPORT OF REMOVAL ACTION AND INITIATION OF REMEDIATION SOILS CONTAINING PETROLEUM HYDROCARBONS FORMER GARAGE AND POLE YARD OFFICE SOUTHERN CALIFORNIA EDISON VISALIA POLE YARD

INTRODUCTION

This report documents the methods and results of the activities conducted to remove and initiate remediation of soils containing petroleum hydrocarbons beneath both the former Visalia Service Center (VSC) Garage and former Pole Yard Office. The location of these two areas, and other site features, are shown on the Site Plan, Figure 1. This work was conducted in accordance with a Work Plan submitted to the Department of Toxic Substances Control (DTSC) in November, 1994.

SCE completed demolition of structures associated with the former VSC and Pole Yard operations in August, 1994. Following demolition of the VSC, subsurface soil sampling was conducted beneath the vehicle hoists and wash rack clarifier in the former Garage building. Initial analytical results showed hydraulic oil was present immediately beneath the east vehicle hoist. A follow-up subsurface investigation was conducted in September, 1994 to define the extent of the hydraulic oil release.

Soil sampling conducted beneath and adjacent to the former Pole Yard Office in 1990, during UST removals, indicated a diesel release beneath the west wall of the building. Further investigation to fully define the release was conducted in September, 1994, to support the Work Plan for this removal action.

The following sections describe the soil removal action, verification sampling and analytical protocols; and initiation of ex-situ bioremediation of the impacted soils to reduce hydrocarbon concentrations to below hazardous levels.

SOIL REMOVAL AND VERIFICATION SAMPLING

SERVICE CENTER GARAGE

The soil containing hydraulic oil was removed with an excavator to a depth of fifteen feet, on December 6, 1994. The excavation extended laterally to the four

previous sampling points (documented in the Work Plan) where no hydrocarbons were detected. The location and dimensions of the excavation are shown on the Hydraulic Oil Excavation Plan, Figure 2. The excavated material was transported to the landfarm plot, located inside the slurry wall, north of the old Pole Yard Office. The plot location is shown on the Site Plan.

Verification Sampling

Following soil removal, two soil samples were obtained from the bottom of the excavation; one in the west half and one in the east half, as shown on Figure 2. Samples were collected in a clean glass jar with teflon-lined lid, from an excavator bucket of freshly excavated soil. The samples were designated HOREM-1 (west sample) and HOREM-2 (east sample). After acquisition, the samples were hand-delivered to an on-site mobile laboratory, operated by Calscience Environmental Laboratories, Inc. Standard chain-of-custody procedures were followed.

Analytical Program

Both soil samples were analyzed for TPH as hydraulic oil (EPA Method 8015, Modified), using a hydraulic oil standard.

Analytical Results

Both soil samples were below the detection limit (10mg/Kg) for TPH-Hydraulic Oil, as summarized below. A copy of the Analytical Report, Quality Assurance Summary, and chain-of-custody are presented in Appendix A.

SAMPLE NUMBER	Hydraulic Oil Concentration (mg/Kg)
HOREM-1	ND
HOREM-2	ND

POLE YARD OFFICE

Soil containing diesel was removed with an excavator to a depth of 25 feet, on December 6, 1994. The excavation was centered on the boring which indicated diesel during the recent site characterization (KB-3, Appendix 2 of Work Plan), and extended laterally to where there was no indication of the presence of diesel. The dimensions of the intial excavation is shown on the Diesel Excavation Plan, Figure 3. Additional excavation was required on the north wall of the excavation, which is also shown on the Figure. The excavated material was transported to the landfarm plot.

Verification Sampling

Following initial excavation, soil samples were obtained to verify adequacy of the removal action. A soil sample was obtained from the middle of each sidewall of the excavation, at a depth of twenty feet. These samples, located as shown on Figure 3, were designated VPY-DREM-1 (north wall), VPY-DREM-2 (east wall), VPY-DREM-3 (west wall), and VPY-DREM-4 (south wall). Two samples were obtained from the bottom of the excavation, at a depth of twenty-five feet, at the locations shown on the Figure. They were designated VPY-DREM-5 and VPY-DREM-6. Samples were collected in a clean glass jar with teflon-lined lid, from an excavator bucket of freshly excavated soil. Following collection and labeling, the samples were hand-delivered to the mobile laboratory.

Initial analytical results of the north wall sample (VPY-DREM-2) indicated the presence of diesel, at a concentration of 274 mg/Kg. Additional excavation was conducted in the north wall, as shown on Figure 3. Following additional removal, another sample (designated VPY-DREM-7) was collected from the north wall extension, at a depth of twenty feet.

Analytical Program

All soil samples were analyzed for TPH as diesel (EPA Method 8015, Modified), by the Calscience mobile laboratory.

Analytical Results

All soil samples obtained from the final limits of the excavation were below the detection limit (10 mg/Kg) for diesel, as summarized below. A copy of the Analytical Report, Quality Assurance Summary, and chain-of-custody are presented in Appendix A.

SAMPLE NUMBER	Hydraulic Oil Concentration (mg/Kg)
VPY-DREM-1	ND
VPY-DREM-2	274
VPY-DREM-3	ND
VPY-DREM-4	ND
VPY-DREM-5	ND
VPY-DREM-6	ND
VPY-DREM-7	ND

SOIL REMEDIATION

The excavated soil from the vehicle hoist and Pole Yard Office were spread out to uniform thickness of approximately one foot at the landfarm plot. A berm of clean imported soil was then constructed around the plot. Treatment consists of weekly tilling to aerate the soil, maintenance of proper moisture, and monthly addition of fertilizer to maintain appropriate nutrient content in the soil.

EXCAVATION BACKFILL

Following verification of the adequacy of removal actions in the two excavations, they were backfilled with clean, imported sand. Since the area where the vehicle hoist excavation is located may be used in the future for industrial/commercial purposes, an engineered backfill was performed. A copy of the compaction report, prepared by Central Valley Testing, Inc., is presented in Appendix B. The Pole Yard Office excavation was backfilled in a similar manner, but was not tested.

If there are any questions or comments on this report, please contact the undersigned at (818) 302-4033, or George Becker, at (818) 302-2216.

No. 1180
CERTIFED
ENGINEERING
CECOLOGIST

OF CALIFORNIA

Respectfully Submitted,

Kandal I Meidnes

Randall S. Weidner CEG 1180

Attachments:


Figure 1 - Site Plan


Figure 2 - Hydraulic Oil Excavation Plan


Figure 3 - Diesel Excavation Plan

Appendix A - Laboratory Reports Appendix B - Compaction Report

FIGURES







EXPLANATION

⑤_{KB-3} Site characterization boring

 $^{
m VPY-DREM-4}$ Number and location of post-excavation soil sample 274 concentration, $_{
m mg}/{\rm kg}$

SCALE: 1" = 10'

DIESEL EXCAVATION PLAN
VISALIA POLE YARD OFFICE

PROJ. REF. NO.

FIGURE 3

APPENDIX A

Laboratory Reports



ANALYTICAL REPORT

Date Sampled:	12/06/94
Date Received:	12/06/94
Date Extracted:	12/06/94
Date Analyzed:	12/06/94
Work Order No.:	294-12-002
Method:	EPA 8015M
Page 1 of 1	
	Date Received: Date Extracted: Date Analyzed: Work Order No.: Method:

All total petroleum hydrocarbon concentrations are reported in mg/kg (ppm) using diesel fuel as a standard.

Sample Number	Concentration	Reportable <u>Limit</u>
VPY-DREM-1	ND	10
VPY-DREM-2	274	10
VPY-DREM-3	ND	10
VPY-DREM-4	ND	10
VPY-DREM-5	ND	. 10
VPY-DREM-6	ND	10
VPY-DREM-7	ND	10
Method Blank	ND	10

Reviewed and Approved

William H. Christensen Deliverables Manager on /2 1/5+1994

ND denotes not detected at indicated reportable limit.

Each sample was received by CEL chilled, intact, and with chain-of-custody attached.

Mobile Operations

11631 Seaboard Circle, Stanton, CA 90680

TEL: (714) 895-5494



QUALITY ASSURANCE SUMMARY

Method EPA 8015M-Diesel

Southern California Edison Company

Work Order No.:

294-12-002

Page 1 of 1

Date Analyzed:

12/06/94

Matrix Spike/Matrix Spike Duplicate

Sample Spiked: VPY-DREM-1

Analyte	MS%REC	MSD%REC	Control <u>Limits</u>	%RPD	Control <u>Limits</u>
Total Petroleum Hydrocarbons	91	96	55 - 135	5	0 - 30

Reviewed and approved:

William H. Christensen

Deliverables Manager

Mobile Operations

11631 Seaboard Circle, Stanton, CA 90680

TEL: (714) 895-5494

on 12/5/1994.



ANALYTICAL REPORT

Southern California Edison Company	Date Sampled:	12/06/94
Environmental Affairs	Date Received:	12/06/94
P.O. Box 800, Room 405, GO 1	Date Extracted:	12/06/94
Rosemead, CA: 91770	Date Analyzed:	12/06/94
	Work Order No.:	294-12-002
Attn: Randy Weidner	Method:	EPA 8015M
RE: Visalia Pole Yard	Page 1 of 1	
		•

All total petroleum hydrocarbon concentrations are reported in mg/kg (ppm) using hydraulic oil as a standard.

Sample Number	Concentration	Reportable <u>Limit</u>
VPY-HOREM-1	ND	10
VPY-HOREM-2	ND	10
Method Blank	ND	10

Reviewed and Approved

William H. Christensen

on <u>/2 //(749</u>94

Deliverables Manager

ND denotes not detected at indicated reportable limit.

Each sample was received by CEL chilled, intact, and with chain-of-custody attached.

Mobile Operations

11631 Seaboard Circle, Stanton, CA 90680

TEL: (714) 895-5494



QUALITY ASSURANCE SUMMARY

Method EPA 8015M-Hydraulic Oil

Southern California Edison Company

Work Order No.:

294-12-002

Page 1 of 1

Analyte

Date Analyzed:

12/06/94

Matrix Spike/Matrix Spike Duplicate

Sample Spiked: VPY-HOREM-1

MS%REC MSD%REC Control **Limits**

%RPD

Control Limits

Total Petroleum Hydrocarbons

101

103

55 - 135

2.

0 - 30

Reviewed and approved:

William H. Christensen

Deliverables Manager

Mobile Operations

11631 Seaboard Circle, Stanton, CA 90680

TEL: (714) 895-5494

CALSCIENCE ENVIRONMENTAL LABORATORIES, INC.

294-12-002

11631 SEABOARD CIRCLE STANTON, CA 90680 TEL: (714) 895-5494 • FAX: (714) 894-7501

CHAIN	OF CUSTODY	RECORD
Date	12/6/94	
	1	4

LABORATORY CLIENT: ADDRESS:	SCE		· · · · · · · · · · · · · · · · · · ·		1	1	~ 0	ME / NUI	. /,	12 Colores	Visalin	Pole Yara	
COTY ROSEMEAU TEL:	Box 800 Room 405 STATE OA FAX: (818)	50.1	ZIP 91	770	PROJ	LERIS	SIGNA	La TURE/	ndy	Weider	ed	90 1 2 2 4 1 2 2 3 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	na ta i urti
SAME DAY (Se	(\$/8) 3 HR)², 125% □ 24 HOURS, 100% re based on working hours of 8:30 a.m 5:30 p.m., M	☐ 48 HOUR		□ 72 H	OURS ³ ,	,25%	□ 5	DAYS ot apply to	□ 10	O DAYS C		EN REPORT, 10%	b
	ONS/BEQUIREMENTS:			:		<u></u>		T:		ROUTINE MB, MS/MSD LCS as applie	, Surrogates, cable.	RWQCB Report F	
SAMPLE ID	LOCATION/DESCRIPTION	DATE	PLING	Come.	TER	luta.	JIR Grah	SOLIO/ SOIL/ FILTER	NO. OF Contars		ANALYSES	REQUIRED	
VPY-DREN-1		12/6/94						S	i	118015	Diesel	*.	
-2		1					,	S	. t	1	<u> </u>		•
-3								S	. (•		
- 4								S	1			· · · · · · · · · · · · · · · · · · ·	
-5								S	(50 · · · · · · · · · · · · · · · · · · ·		
-6							•	c	1.		-		
↓ -7								S	1	1			
VPY- HOREM -1								S	7	LL 8015	Hydrashi	0.1	
NPY-HOREM-2								S	l	n	11		
												1, 1	
Relinquistred by: (Sign	el su entres 12/	6/94	Received Received			2/2	566-				Date: 12/6/	194 5	ic pm
Relinquished by: (Sign	1 1		Received	by: (Sign	ature) (D	/				Date:	Tim	
Relinquished by: (Sign	riatufé)		Received	or Labor	atory b	Sid	ature)	1			Date: 12//	2/44 7	1)6

APPENDIX B

Compaction Report



CENTRAL VALLEY TESTING, Inc.

materials testing and inspection services soils and environmental investigations

Report No. 94-1478

January 4, 1995

FOR: Paul Dunn

Dunn's Sand

15602 Ave. 286

Visalia, California 93291

PROJECT:

Edison Poleyard, Visalia, California.

SUBJECT:

Spot soil density tests taken in Pit Backfill.

TESTS WERE PERFORMED BY: F. Rodriguez on December 7, 8 and 9, 1994.

I. MAXIMUM DENSITY OF SOIL:

MATERIAL NO.	MATERIAL <u>IDENTIFICATION</u>		M DRY DENSI BS/CU.FT.	TY	OPTIMUM MOISTURE %
1	Sand		114.6		8.1
II. FIELD DENS	ITY TESTS	BELOW	FIELD	FIELD	

TEST NO.	TEST LOCATION	LOT MAT NO. NO.	BELOW EXISTING GRADE,IN.	FIELD DENSITY LBS,CU.FT.	FIELD MOIS <u>TURE</u>	RELATIVE COMPACTION
1	North Sector	,	180-186	110.4	12.3	96.3
2	East Sector		156-162	112.8	12.7	98.4
3	South Sector		132-138	112.2	12.0	97.9
4	West Sector		108-114	111.3	12.3	97.9
5	Central Sector		84-90	112.6	9.7	98.3
6	North Sector		60-66	111.4	10.1	97.2

Page 2 Paul Dunn Report No. 94-1478

TEST NO.	TEST LOCATION	LOT MAT NO. NO.	BELOW EXISTING GRADE,IN.	FIELD DENSITY LBS,CU.FT.	FIELD MOIS TURE	RELATIVE COMPACTION
7	East Sector	\$	36-42	112.4	12.1	98.0
8	South Sector		12-18	112.1	12.4	97.8

Central Valley Testing, Inc.

Dennilo R. My ans

cc: City of Reedley DM/rr

Dennis R. Myers Director of Operations

